



Philips Firmware Upgrade Information

| | | | |
|---------------------|-------------------|-------------|--|
| Upgrade for type: | PCDV5016K/40 | Retail | → Drive type number on label. |
| | PCDV5016B/40 | Black bulk | |
| | PCDV5016G/40 | Grey bulk | |
| | PCDV5016S/40 | Silver bulk | |
| | PCDV5016K/45 | Retail | |
| | SPD2200BK/00 | | |
| | SPD2210BK/00 | | |
| | SPD2210SK/00 | Silver | |
| | SPD2200SD/97 | Silver | |
| Upgrade for string: | PCDV5016P1 | | → Drive name as seen in Windows [™] |
| From firmware: | P1.x | | |
| To new firmware: | P1.3 | | |
| Date: | 16 September 2005 | | |

Version History

Initial Release P1.1

Changes from firmware P1.1 to P1.2

- Released 4 May 2005.
- Reduced UDMA-5 to UDMA-2 speed to improve stability.
- Solved issue, which prevented installation of Suse 9.x Linux.
- Improved playability of Audio CDs.

Changes from firmware P1.2 to P1.3

- Released 16 September 2005.
- Improved stability.



Philips does not and can not warrant the performance of/the results you may obtain using this software. At no time, Philips can held liable for any damages including (but not limited to) lost profits or consequential damages or for any claim by any other party.